

Item: 40-D41-1101N

A



1. 圖 A 爲客戶收到產品時的組裝狀態.

Picture(A) the final status clients received.



2. 圖 B 請將東帶剪下並將東帶及固定彈簧 去除。

Picture(B) cut the cable tie, then take out the cable tie and the spring.

固定彈簧(fixed spring)



護蓋(Cover)

3. 圖 C 裝上護蓋.

Picture(C) install the cover